00862.002789





IN THE UNITED STATES PATENT AND TRADEMARK OFFICE

In re Patent of:)	
HIROKI HIYAMA ET AL.		:)	Examiner: James M. Hannett
Appln. No.: 09/291,006)	Group Art Unit: 2612
Filed: April 14, 1999)	Certificate
For:	SOLID-STATE IMAGE SENSING APPARATUS AND METHOD OF) :	FEB 2 8 2006
	OPERATING THE SAME)	of Correction
U.S. Patent No.: 6,963,372 B1)	
Issued:	November 8, 2005)	February 22, 2006
Commi	ssioner for Patents		

CERTIFICATE OF CORRECTION UNDER RULES 322 AND 323

Sir:

P.O. Box 1450

Alexandria, VA 22313-1450

It is respectfully requested that a Certificate of Correction be issued by the

Patent and Trademark Office due to errors which appear in the printed patent as a result of

Patent and Trademark Office mistakes, and mistakes of a clerical, typographical, or minor

02/24/2006 JADDO1 00000076 6963372

character, which were not the fault of the Patent and Trademark Office. A Certificate of

100.00 OP

Correction form, in duplicate, is enclosed.

Accompanying this letter is a check for \$100.00 to cover the statutory fee for such Certificate of Correction.

Patentees' undersigned attorney may be reached in our New York office by telephone at (212) 218-2100. All correspondence should continue to be directed to our address given below.

Respectfully submitted,

John A. Krause

Attorney for Patentees Registration No. 24,613

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 Facsimile: (212) 218-2200

553724V1

UNITED STATES PATENT AND TRADEMARK OFFICE

CERTIFICATE OF CORRECTION

PATENT NO.

6,963,372 B1

DATED

November 8, 2005

INVENTOR(S) :

HIROKI HIYAMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"JP 5-18309 3/1983" should read --JP 5-18309 3/1993--; and "JP 4-61573 2/1992" should be deleted.

COLUMN 2

Line 42, "t^{35p}," should read --t_{35p},--.

COLUMN

Line 29, "drop" should read --drop of--;.

COLUMN 9

Line 45, "t₂₅₁" should read --t₂₅,--.

MAILING ADDRESS OF SENDER:

PATENT NO. US 6,963,372 B1

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

553724v1

.



PRINTER'S TRIM LINE

UNITED STATES PATENT AND TRADEMARK OFFICE CERTIFICATE OF CORRECTION

PATENT NO.

6,963,372 B1

DATED

November 8, 2005

INVENTOR(S) :

HIROKI HIYAMA ET AL.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

ON COVER PAGE AT (56) FOREIGN PATENT DOCUMENTS

"JP 5-18309 3/1983" should read --JP 5-18309 3/1993--; and "JP 4-61573 2/1992" should be deleted.

COLUMN 2

Line 42, "t^{35p}," should read --t_{35p},--.

COLUMN

Line 29, "drop" should read --drop of--;.

COLUMN 9

Line 45, "t₂₅₁" should read --t₂₅,--.

MAILING ADDRESS OF SENDER:

FITZPATRICK, CELLA, HARPER & SCINTO 30 Rockefeller Plaza New York, New York 10112-3801 (212) 218-2100 - Telephone (212) 218-2200 - Facsimile PATENT NO. US 6,963,372 B1

No. of add'l. copies @ 30¢ per page

Form PTO 1050 (Rev. 3-82)

553724v1

